Laser Order Process Flow

STEP 1 – CREATE PARTS AND QUOTE



STEP 2 – RAISE PRODUCTION ORDER/JOB



STEP 3 – DESPATCH AND INVOICE