

Show all Inspection/Calibration Items

Overview:

The 'Show All Inspection/Calibration Items' window enables the users to view all the items entered into the system for inspection/calibration. This window also displays the last inspection date, the next inspection date, who is responsible to ensure the item is inspected and whether the items are active or non-active. The information displayed can be customised by using the drop-down lists or tick boxes.


To View All Inspection/Calibration Items

From the OPTO ribbon, select the "Quality" tab then **click** on the 'Insp/Cal' icon (1) to bring up the 'Show All Inspection/Calibration Items' window. Then **click** the 'Refresh' icon (2) to fill the table.

The screenshot shows the 'Show All Inspection/Calibration Items' window. The ribbon is set to 'QUALITY'. The 'Insp/Cal' icon is highlighted with a red circle (1). The 'Refresh' icon is highlighted with a red circle (2). The window displays a table of inspection items.

Calibration ID	Description	Act	Insp Req	Int/Ext	First Insp	Freq	Next Insp	R/Pos	Position Name	Resp Name	Loc	Div	Serial No	ToGo	Last Insp
1 XXXX	TEST	Yes	Yes	Int	22/07/12	1	23/07/13								-2031
2 COM203	500KW Air Compressor - Royce	Yes	Yes	Int	25/07/14	12	27/07/15	1015	Quality Control Co	Susan PAINTER	WELD	1	RC7557P	-1297	04/08/14
3 C1	kcdsnjckdsnevcdskjvdsKJvhbsDJK	No	No	Int											-18672
4 C3	jvdjvoidj	No	No	Int											-18672
5 C10		No	No	Int											-18672
6 C12		No	No	Int											-18672
7 WEL2002	ABC Mig Welder	Yes	Yes	Int	20/04/10	6	20/10/10	1010	General Manager						-3038
8 COM2201	200KW Compressor - Royce	Yes	Yes	Int	02/11/11	12	01/11/12	1015	Quality Control Co	Susan PAINTER	WELD	0001	RC22214P	-2295	04/08/14
9 TEST	test	No	No	Int	01/01/14	12	01/12/13								-1170
10 COM201	200KW Compressor - Royce	Yes	Yes	Int	02/11/11	12	04/08/15	1015	Quality Control Co	Susan PAINTER	WELD	0001	RC22214P	-1289	04/08/14
11 WEL003	CBA Tig Welder	Yes	Yes	Int	21/11/09	6	21/05/10	1010	General Manager						-3190
12 COM202	185KW Compressor - Royce	Yes	Yes	Int	02/03/10	12	02/03/11	3110	Supervisor Machin	Colin COASTLY	EQ-ST	0001	RC22878P	-2905	
13 AIR252	Air Drill	No	No	Int	02/03/10	12	02/03/11						XP24569787AP	-2905	01/08/14
14 WEL001	ABC Mig Welder	Yes	Yes	Int	01/01/10	6	16/10/18	3010	Production Manag	Ian CAPTAIN	3002	0001	996-214	-120	16/04/18
15 C2	jodsfvkljogvluhgreauiquhyal	No	No	Int											-18672
16 C13		No	No	Int											-18672
17 3000-1	pkhlluyutjtderes	No	No	Int	01/01/14	6	04/12/15								-1167
18 AIR250	Air Grinder	Yes	Yes	Int	22/04/13	1	23/04/13	3110	Supervisor Machin	Colin COASTLY	BIN1001	0002	AP40007587	-2122	22/04/13
19 N001	new record	No	No	Int	01/01/16	2	25/05/16								-994
20 WEL002	ABC Mig Welder	Yes	Yes	Int	20/04/10	6	20/10/10	1010	General Manager						-3038
21 AIR251	Air Impact Wrench	Yes	Yes	Int	22/05/05	1	22/05/06	3110	Supervisor Machin	Colin COASTLY	BIN1001	0002	IM1000234587	-4650	
22 C20		No	No	Int											-18672

Records can be viewed or edited from this window, by **dbl-clicking** on the 'Calibration ID' for that item to open the 'Inspection/Calibration Items' window.



Press <F9> to save any changes made to the item.